



# Huawei P10 USB Port Replacement


This video is about how to repair the broken USB port of Huawei P10.

Written By: Eric

P10

## USB Board

### Repair Guide



## INTRODUCTION

[video: [https://www.youtube.com/watch?v=TIN8\\_W8sFvI](https://www.youtube.com/watch?v=TIN8_W8sFvI)]

This video shows you how to repair the broken usb port of huawei p10. If your phone can not charge or connect to laptop, follow this repair guide to fix the broken usb port.

Step1 Open the battery cover of Huawei P10

Step2 Remove the broken USB board

Step3 Install a new USB board

Step4 Instal battery cover of huawei P10

This document was last generated on 2017-07-12 09:36:31 PM.